



SNS COLLEGE OF TECHNOLOGY

Coimbatore-35

An Autonomous Institution

Accredited by NBA – AICTE and Accredited by NAAC – UGC with 'A++' Grade

Approved by AICTE, New Delhi & Affiliated to Anna University, Chennai



DEPARTMENT OF MECHATRONICS ENGINEERING

UNIT IV – CNC PROGRAMMING

COORDINATE SYSTEM & STRUCTURE OF A PART PROGRAM



COORDINATE SYSTEM



1. Machine Coordinates:

1. The CNC machine has its own coordinate system, often called the machine coordinates. It represents the physical dimensions of the machine.

2. Work Coordinates:

1. The work coordinates define the position of the part in relation to the machine. This system is set based on the part's dimensions and location on the machine table.

3. Origin:

1. Establish a reference point (origin) for your part. It's a common practice to set the origin at one of the corners of the part or at the center, depending on your preference and the machining requirements.

4. Axis Orientation:

1. Understand the orientation of the machine's axes (X, Y, and Z). Usually, X is horizontal, Y is vertical, and Z is the depth.



STRUCTURE OF A PART PROGRAM



- **Tool Selection:**

Choose the appropriate cutting tools based on the part's geometry and material.

- **Tool Paths:**

Plan the tool paths that the CNC machine will follow to create the part. Consider the order of operations and the sequence of cuts.

- **G-code Commands:**

Use G-code commands to control the machine. Common commands include G00 (rapid positioning), G01 (linear interpolation/movement), G02/G03 (circular interpolation), M03/M04 (spindle on/off), M05 (spindle stop), etc.

- **Programming Blocks:**

Organize your program into blocks. Each block typically contains one or more G-code commands. Use line numbers to help with program navigation and troubleshooting.



STRUCTURE OF A PART PROGRAM



- **Feed Rates and Speeds:**

Specify feed rates (how fast the tool moves through material) and spindle speeds based on the material being cut and the tool being used.

- **Tool Offsets:**

Consider tool offsets to compensate for the tool's physical dimensions. These offsets ensure the tool cuts precisely where it's supposed to.

- **Coolant and Lubrication:**

Include commands for coolant and lubrication if needed. This is crucial to prevent overheating and extend tool life.

- **Safety Precautions:**

Add safety measures, such as retracting the tool to a safe height between operations, to avoid collisions.



STRUCTURE OF A PART PROGRAM



N10 G90 G54 ; Absolute coordinates, work coordinate system G54

N20 G00 X0 Y0 Z0 ; Rapid positioning to the starting point

N30 M03 S500 ; Start spindle at 500 RPM

N40 G01 X10 Y5 Z-2 F100 ; Linear cut to point (10, 5, -2) at a feed rate of 100 units/minute

N50 G02 X15 Y10 I2 J3 ; Circular cut with a radius of 2 units, center at (15, 10)

N60 M05 ; Stop spindle

N70 G00 Z5 ; Rapid retract to Z5

N80 M30 ; End of program