# DEFECTS IN WELDING

1. In completed fusion
2. Cracks
3. Porosity
4. Undercut
5. Distortion
6. Slag inclusion
7. Lamellar teaming
8. Overlapping

In completed fusion

Cracks

Porosity

Distortion

Slag inclusion

Lamellar teaming

Cracks

Overlapping

Over Lap