

REASON FOR MAKING THE STROKE LENGTH GREATER THAN WORK LENGTH

1. To obtain the good surface finish.
2. To avoid rubbing of the tool on the work surface
3. To allow sufficient time for giving cross feed
4. To allow sufficient time for the clapper box to attain its proper seat for cutting
5. To allow the ram for obtaining the proper cutting speed