





AN AUTONOMOUS INSTITUTION

Approved by AICTE New Delhi & Affiliated to Anna University Chennai Accredited by NBA & Accredited by NAAC with "A+" Grade, Recognized by UGC

COIMBATORE

DEPARTMENT OF CIVIL ENGINEERING

19CEB204 – CONSTRUCTION MATERIALS

II YEAR / III SEMESTER

Unit 2 : Lime – Cement – Aggregates Topic 3 : Manufacturing process of Cement







- Raw materials employed in the manufacture of cement are extracted by quarrying in the case of hard rocks such as limestones, slates, and some shales, with the aid of blasting when necessary.
- Softer rocks such as chalk and clay can be dug directly by excavators.
- The excavated materials are transported to the crushing plant by trucks, railway freight cars, conveyor belts, or ropeways.
- ➤ They also can be transported in a wet state or slurry by pipeline.



Extraction and Processing





10/17/2022



Manufacture of Cement



- > There are four stages in the manufacture of Portland cement:
 - 1. crushing and grinding the raw materials,
 - 2. blending the materials in the correct proportions,
 - 3. burning the prepared mix in a kiln, and
 - 4. grinding the burned product, known as "clinker," together with some5 percent of gypsum (to control the time of set of the cement)



Manufacture of Cement



- ➤ The three processes of manufacture are known as the
 - o wet,
 - o dry,
 - semidry processes
- \blacktriangleright They are so termed when the raw materials are
 - o ground wet and fed to the kiln as a slurry,
 - ground dry and fed as a dry powder,
 - ground dry and then moistened to form nodules that are fed to the kiln.







- All except soft materials are first crushed, often in two stages, and then ground, usually in a rotating, cylindrical ball, or tube mills containing a charge of steel grinding balls.
- This grinding is done wet or dry, depending on the process in use, but for dry grinding the raw materials first may need to be dried in cylindrical, rotary dryers.
- Soft materials are broken down by vigorous stirring with water in wash mills, producing a fine slurry, which is passed through screens to remove oversize particles.



Crushing and Grinding





10/17/2022







- A first approximation of the chemical composition required for a particular cement is obtained by selective quarrying and control of the raw material fed to the crushing and grinding plant.
- In the dry process these mixes are stored in silos; slurry tanks are used in the wet process.
- Thorough mixing of the dry materials in the silos is ensured by agitation and vigorous circulation induced by compressed air.







- In the wet process the slurry tanks are stirred by mechanical means or compressed air or both.
- The slurry, which contains 35 to 45 percent water, is sometimes filtered, reducing the water content to 20 to 30 percent, and the filter cake is then fed to the kiln.
- > This reduces the fuel consumption for burning.















- The earliest kilns in which cement was burned in batches were bottle kilns, followed by chamber kilns and then by continuous shaft kilns.
- The shaft kiln in a modernized form is still used in some countries, but the dominant means of burning is the rotary kiln.
- These kilns—up to 200 metres (660 feet) long and six metres in diameter in wet process plants but shorter for the dry process—consist of a steel, cylindrical shell lined with refractory materials.







- They rotate slowly on an axis that is inclined a few degrees to the horizontal.
- The raw material feed, introduced at the upper end, moves slowly down the kiln to the lower, or firing, end.
- The fuel for firing may be pulverized coal, oil, or natural gas injected through a pipe.
- The temperature at the firing end ranges from about 1,350 to 1,550 °C (2,460 to 2,820 °F), depending on the raw materials being burned.















- Some form of heat exchanger is commonly incorporated at the back end of the kiln to increase heat transfer to the incoming raw materials and so reduce the heat lost in the waste gases.
- ➤ The burned product emerges from the kiln as small nodules of clinker.
- These pass into coolers, where the heat is transferred to incoming air and the product cooled.







- The clinker may be immediately ground to cement or stored in stockpiles for later use.
- In the semidry process the raw materials, in the form of nodules containing 10 to 15 percent water, are fed onto a traveling chain grate before passing to the shorter rotary kiln.
- Hot gases coming from the kiln are sucked through the raw nodules on the grate, preheating the nodules.







- Dust emission from cement kilns can be a serious nuisance.
- In populated areas it is usual and often compulsory to fit cyclone arrestors, bag-filter systems, or electrostatic dust precipitators between the kiln exit and the chimney stack.
- More than 50 percent of the emissions from cement production are intrinsically linked to the production of clinker and are a by-product of the chemical reaction that drives the current process.







- There is potential to blend clinker with alternative materials to reduce the need for clinker itself and thus help reduce the climate impacts of the cement-making process.
- Modern cement plants are equipped with elaborate instrumentation for control of the burning process.
- Raw materials in some plants are sampled automatically, and a computer calculates and controls the raw mix composition.
- ➤ The largest rotary kilns have outputs exceeding 5,000 tons per day.















- The clinker and the required amount of gypsum are ground to a fine powder in horizontal mills similar to those used for grinding the raw materials.
- The material may pass straight through the mill (open-circuit grinding), or coarser material may be separated from the ground product and returned to the mill for further grinding (closed-circuit grinding).
- Sometimes a small amount of a grinding aid is added to the feed material.
- For air-entraining cements (discussed in the following section) the addition of an air-entraining agent is similarly made.
- Finished cement is pumped pneumatically to storage silos from which it is drawn for packing in paper bags or for dispatch in bulk containers.











Cement Manufacturing



Crushers Old tires Shale = Alumina = Fe-ox Limestone = CaO Quarry Silica Rotary Kiln Sypsu Portland Grinder Kurt Friehauf - friehauf@kutztown.edu

- 1. Limestone, shale, silica, and iron oxides are guarried from the ground. (Some limestones already contain enough silica).
- 2. Rock materials are run through a crusher that turns rock into smaller pieces.
- 3. Crushed limestone + silica + shale + iron oxides are mixed together and run through a rotary kiln.
- 4. Rotary kiln continuously mixes ingredients and "calcines" limestone so that CO, is driven off, forming clinker.
- Cement 5. Clinker is ground to fine powder and mixed with gypsum (helps moderate how fast the cement "sets), then bagged for sale.



Cement Manufacturing











Raw Mill





Cooler



Preheater and Kiln



Blending and Storage Silo



10/17/2022





Thank You!!

10/17/2022