

SNS COLLEGE OF TECHNOLOGY (Autonomous) DEPARTMENT OF AERONAUTICAL ENGINEERING



## UNIT-4 TESTING AND INSPECTION

P.KALPANADEVI,AP/AERO -19AEO302 AS&E



SNS COLLEGE OF TECHNOLOGY (Autonomous) DEPARTMENT OF AERONAUTICAL ENGINEERING



# SYMPTOMS OF FAILURE Symptoms of failure can be carried out by FAILURE ANALYSIS and

## TROUBLE SHOOTING

P.KALPANADEVI,AP/AERO -19AEO302 AS&E




SNS COLLEGE OF TECHNOLOGY



(Autonomous)

DEPARTMENT OF AERONAUTICAL ENGINEERING

#### SIX STEP IN TROUBLE SHOOTING







### SYMPTOMS OF FAILURE

#### **1. SYSTEM RECOGNITION:**

The first step in trouble shooting – involves having knowledge of engine condition that is not normal and knowing to what extent the fault is affecting the engines performance.





WSTITUTION'S www.snsgroups.com

(Autonomous) DEPARTMENT OF AERONAUTICAL ENGINEERING

#### **2. SYSTEM ELABORATION:**

It is the next logical step, once a fault or malfunction has been detected. Test equipment helps the technician to evaluate the performance of the engine and its components. The technicians should use these aids to assess the effects of the symptoms and to provide additional information to further define the symptoms.